



Cracked piers



Cracked piers



Foundation in rear sawtooth is not strong and different materials used



Floor joists are termite infested



Ceiling joists and collar ties cut through in a few locations



New framing is just blocking not adding strength




Trim does not match on the sawtooth addition



Interior framing has water damage, sheetrock ceiling has mold



Interior wall framing is rotten, mold on ceiling



Sawtooth not visible from street on east side of house



Sawtooth not visible from street on west side of house