EXHIBIT "A"

Concrete Repair Cost Proposal Form for Fredrick Douglass Gym Base Bid

1 General Conditions:				
a.General Conditions/Miscellaneous:		<u>1</u> LS		\$7,000.00
b.Temporary Shoring		<u>1</u> LS		\$4,000.00
(Shoring design to be by Florida Registered Engineer)				
2 Additional Demolition and Concrete Repair:				
a. Repair of Top of Wall Tie Beam West and East Elevations	SK-1	60 CF	\$325.00	\$19,500.00
b. Repair of Top of Wall Trie Beam North and South Elevations	SK-2	10 CF	\$325.00	\$3,250.00
c. Removal and Replacement of Widnow Sill w/New Rebar and 3000 psi Concrete		20 CF	\$325.00	\$6,500.00
d. Infill of Cut Block Wall w/3000 psi Concrete		10 CF	\$325.00	\$3,250.00
e. Concrete Repairs at Widnow Header Beam (BASF S 440)		50 CF	\$325.00	\$16,250.00
f. Concrete Repairs at Window Header Beam (BASF N 425)	SK-4,5,6	10 CF	\$335.00	\$3,350.00
g. Concrete Repairs at Mid Wall Tie Beam (BASF S440)		20 CF	\$325.00	\$6,500.00
h. Concrete Repairs at Mid Wall Tie Beam (BASF N425)		10 CF	\$335.00	\$3,350.00
i. Concrete Repairs at Columns (BASF S 440)	SK-4,5,6	110 CF	\$325.00	\$35,750.00
3 Miscellaneous:				
a. Epoxy Injection of Cracking a Columns and Tie Beams	SK-7	350 LF	\$60.00	\$21,000.00
b. Heli-Fix Anchors for Masonry Not Tied in to Wall		50 LF	\$65.00	\$3,250.00
c. #3 Rebar for Concrete Repairs		150 LF	\$0.40	\$60.00
d. #4 Rebar for Concrete Repairs		150 LF	\$0.50	\$75.00
e. #5 Rebar for Concrete Repairs		150 LF	\$0.60	\$90.00
f. Rebar Splice		50 EA	\$30.00	\$1,500.00
g. Vector XP/XPT Anodes		50 EA	\$50.00	\$2,500.00
h. Joist Seat Repair	SK-10	5 EA	\$100.00	\$500.00

TOTAL BASE BID \$137,675.00

ADDITIONAL UNIT PRICES

1 Top of wall tie beam concrete removal, surface preparation and relacement with new concrete:

2 Removal and replacement of existing concrete with new rebar and 3000 psi concrete:

3 Concrete repair using:

3:	BASF 425
	BASF 440
	<1/8 inch
	1/8-1/4 inch
	1/4-3/8 inch

DL Porter O&P Bond and Insurance Markup (NO GC'S)

\$381/CF \$325.00 /CF

\$381/CF

\$325.00 /CF

\$393/CF \$335.00 /CF \$325.00 /CF \$381/CF \$117/LF

\$100.00 /LF \$147/LF \$125.00 /LF \$135.00 /LF \$158/LF

Notes:

- Base Lump Sum (LS) cost on quantities provided in the above cost proposal bid form.
- Unit price pay items will require owner approval of contractor.
- If hidden conditions are identified during the construction/repair efforts Architect shall be notified via a written RFI.
- All above estimated quantities listed in the Schedule of Values (SOV) were based on visual limited-intrusive inspections completed by McCarthy and Associates April 25-26, 2017. The inspections/survey were conducted through site access from ground level or readily accessible areas viewed from a provided onsite lift. The listed quantities shall not be considered an ultimate guarantee of all required repair work. The quantities required to repair actual damaged conditions will be determined after the completion of demolition by the contractor.
- Refer to the primary report from Hayes Cummings Architects PA dated July 15, 2013 for additional information regarding the existing structure identified during our previous survey of the structure.
- Due extensive overlap of the new roofing material at the top perimeter wall and roof deck, there was limited visual access to survey the entire roof perimeter. Quantities of repair at the top of wall tie beam were based on onsite discussions with the contractor and a review of isolated areas open for review during our site visit.