



Legislation Details (With Text)

**File #:** 19-3708      **Version:** 1      **Name:**  
**Type:** Code Violations      **Status:** Passed  
**File created:** 3/7/2019      **In control:** Code Compliance Hearing  
**On agenda:** 3/27/2019      **Final action:** 5/29/2019  
**Title:** Case # 18-2020  
 Robert Chinnis Construction, Inc  
 Robert R. Chinnis - RA  
 506 Southard Street  
 Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
 Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
 Sec. 14-40 Permits in historic districts  
 Sec. 14-262 Request for inspection  
 Officer Jorge Lopez  
 Hand Served: 2-27-2019  
 Initial Hearing: 3-27-2019

Continued from 24 April 2019 for compliance

Count 1: Failure to obtain a permit for plumbing work performed in the rear side exterior of the building. Count 2: Failure to obtain a permit for electrical work performed on the rear side of the building. Count 3: Failure to obtain a certificate of appropriateness for plumbing and electrical work performed on the rear side of the building. Count 4: Failure to obtain a required electrical inspection for electrical work performed on the rear side of the building.

**Sponsors:**

**Indexes:**

**Code sections:**

**Attachments:**

Date	Ver.	Action By	Action	Result
5/29/2019	1	Code Compliance Hearing	Violation Fine	
4/24/2019	1	Code Compliance Hearing	Continuance	
3/27/2019	1	Code Compliance Hearing	Continuance	

**Case # 18-2020**

Robert Chinnis Construction, Inc  
 Robert R. Chinnis - RA  
 506 Southard Street  
 Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
 Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
 Sec. 14-40 Permits in historic districts  
 Sec. 14-262 Request for inspection  
 Officer Jorge Lopez  
 Hand Served: 2-27-2019  
 Initial Hearing: 3-27-2019

**Continued from 24 April 2019 for compliance**

**Count 1:** Failure to obtain a permit for plumbing work performed in the rear side exterior of the building. **Count 2:** Failure to obtain a permit for electrical work performed on the rear side of the building. **Count 3:** Failure to obtain a certificate of appropriateness for plumbing and electrical work performed on the rear side of the building. **Count 4:** Failure to obtain a required electrical inspection for electrical work performed on the rear side of the building.