Legislation Details (With Text)

File #:	18-2443 **Version:** 1	**Name:**	
Type:	Code Violations	**Status:**	Passed
File created:	6/8/2018	**In control:**	Code Enforcement Hearing
On agenda:	1/30/2019	**Final action:**	8/28/2019

Title: Case # 18-536
Brugman Holdings LLC - Owner
Thomas J Sireci, Jr - Registered Agent
10 Hilton Haven Drive C
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions
Director Jim Young
Certified Service: 5-30-2018 - Owner
Certified Service: 5-23-2018 - Registered Agent
Initial Hearing: 6-27-2018

Continued from 31 July 2019 for compliance

Count 1: Failure to obtain an after-the-fact building permit for interior framing of shed and dock behind shed.

Sponsors:

Indexes:

Code sections:

Attachments:

Date	Ver.	Action By	Action	Result
8/28/2019	1	Code Enforcement Hearing	Violation Fine	
7/31/2019	1	Code Enforcement Hearing	Continuance	
6/27/2019	1	Code Enforcement Hearing	Continuance	
5/29/2019	1	Code Enforcement Hearing	Continuance	
4/24/2019	1	Code Enforcement Hearing	Continuance	
3/27/2019	1	Code Enforcement Hearing	Continuance	
2/27/2019	1	Code Enforcement Hearing	Continuance	
1/30/2019	1	Code Enforcement Hearing	Continuance	
11/28/2018	1	Code Enforcement Hearing	Continuance	
10/31/2018	1	Code Enforcement Hearing	Continuance	
9/26/2018	1	Code Enforcement Hearing	Continuance	
7/25/2018	1	Code Enforcement Hearing	Continuance	
6/27/2018	1	Code Enforcement Hearing	Continuance	

Case # 18-536

Brugman Holdings LLC - Owner
Thomas J Sireci, Jr - Registered Agent

10 Hilton Haven Drive C
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions
Director Jim Young
Certified Service: 5-30-2018 - Owner
Certified Service: 5-23-2018 - Registered Agent
Initial Hearing: 6-27-2018

Continued from 31 July 2019 for compliance

Count 1: Failure to obtain an after-the-fact building permit for interior framing of shed and dock behind shed.