



Legislation Details (With Text)

File #: 19-3708 **Version:** 1 **Name:**
Type: Code Violations **Status:** Passed
File created: 3/7/2019 **In control:** Code Compliance Hearing
On agenda: 3/27/2019 **Final action:** 5/29/2019
Title: Case # 18-2020
Robert Chinnis Construction, Inc
Robert R. Chinnis - RA
506 Southard Street
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions
Sec. 14-40 Permits in historic districts
Sec. 14-262 Request for inspection
Officer Jorge Lopez
Hand Served: 2-27-2019
Initial Hearing: 3-27-2019

Continued from 24 April 2019 for compliance

Count 1: Failure to obtain a permit for plumbing work performed in the rear side exterior of the building. Count 2: Failure to obtain a permit for electrical work performed on the rear side of the building. Count 3: Failure to obtain a certificate of appropriateness for plumbing and electrical work performed on the rear side of the building. Count 4: Failure to obtain a required electrical inspection for electrical work performed on the rear side of the building.

Sponsors:

Indexes:

Code sections:

Attachments:

Date	Ver.	Action By	Action	Result
5/29/2019	1	Code Compliance Hearing	Violation Fine	
4/24/2019	1	Code Compliance Hearing	Continuance	
3/27/2019	1	Code Compliance Hearing	Continuance	

Case # 18-2020

Robert Chinnis Construction, Inc
Robert R. Chinnis - RA
506 Southard Street

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-40 Permits in historic districts

Sec. 14-262 Request for inspection

Officer Jorge Lopez

Hand Served: 2-27-2019

Initial Hearing: 3-27-2019

Continued from 24 April 2019 for compliance

Count 1: Failure to obtain a permit for plumbing work performed in the rear side exterior of the building. **Count 2:** Failure to obtain a permit for electrical work performed on the rear side of the building. **Count 3:** Failure to obtain a certificate of appropriateness for plumbing and electrical work performed on the rear side of the building. **Count 4:** Failure to obtain a required electrical inspection for electrical work performed on the rear side of the building.