



## Legislation Details (With Text)

**File #:** 16-9702      **Version:** 1      **Name:**  
**Type:** Code Violations      **Status:** Passed  
**File created:** 6/3/2016      **In control:** Code Compliance Hearing  
**On agenda:** 6/29/2016      **Final action:** 7/27/2016  
**Title:** Case # 16-358  
Frederick L & Diane Covan  
1409 Albury Street 1  
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
Sec. 14-40 Permits in historic districts  
Sec. 14-327 Inspections  
Officer Jorge Lopez  
Certified Service: 5-23-2016  
Initial Hearing: 6-29-2016

In compliance July 3, 2016, request dismissal

Count 1: Renovations and changes on the exterior of this building were done without benefit of the required building permits including the HVAC units which are installed in the set back. Count 2: Renovations and changes on the exterior of this building were done without benefit of the required certificate of appropriateness including the HVAC units which are installed in the set back. Count 3: The HVAC system was installed without the required inspections.

### Sponsors:

### Indexes:

### Code sections:

### Attachments:

Date	Ver.	Action By	Action	Result
7/27/2016	1	Code Compliance Hearing	Dismissed	
6/29/2016	1	Code Compliance Hearing	Continuance	

### Case # 16-358

Frederick L & Diane Covan  
1409 Albury Street 1  
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
Sec. 14-40 Permits in historic districts  
Sec. 14-327 Inspections  
Officer Jorge Lopez  
Certified Service: 5-23-2016  
Initial Hearing: 6-29-2016

### In compliance July 3, 2016, request dismissal

**Count 1:** Renovations and changes on the exterior of this building were done without benefit of the required building permits including the HVAC units which are installed in the set back. **Count 2:** Renovations and changes on the exterior of this building were done without benefit of the required

certificate of appropriateness including the HVAC units which are installed in the set back. **Count 3:**  
The HVAC system was installed without the required inspections.