
Code Case #13-1237
Count 1-Section 18-150 Certificate of Competency Required
Count 2-Section 14-37 Building Permits (fence) required
Photos taken by Code Officer Barbara Meizis on October 9, 2013
Howard Paul Schneider Jr and Howard Paul Schneider IV - Violators





Code Case #13-1237
Count 1-Section 18-150 Certificate of Competency Required
Count 2-Section 14-37 Building Permits (fence) required
Photos taken by Code Officer Barbara Meizis on October 9, 2013
Howard Paul Schneider Jr and Howard Paul Schneider IV - Violators



In the above photo, Mr. Schneider IV is in front and his father Mr. Schneider Jr is next to him to his left.

Code Case #13-1237

Count 1-Section 18-150 Certificate of Competency Required

Count 2-Section 14-37 Building Permits (fence) required

Photos taken by Code Officer Barbara Meizis on October 9, 2013

Howard Paul Schneider Jr and Howard Paul Schneider IV - Violators





Mr. Schneider IV in the photo on the left and Mr. Taurean J Roberts the tenant is in the photo on the right.



As of November 4, 2013, the Stop Work

Order posting had been removed and no After the Fact fence building permit had been applied.