



# Florida Bearings, Inc.

"Friction Management, Fluid Flow and Electro-Mechanical Repair Specialists"

Quotation#

**W4\*57534**

2020 N Rio Grande Ave

Orlando, FL 32804

Phone: 407-843-4153 Fax: 407-843-4154

Tom Robinson trobinson@floridabearings.com

## QUOTATION

**Company:** CH2M HILL OMI  
 TRUMBO POINT ANNEX  
 FLEMING KEY  
 KEY WEST, FL 33040

**Contact:** RICKY COLLINS  
**Phone:** 305-747-5107  
**Fax:** 305-292-5130  
**Email:** arnold.collins@ch2m.com

SALESPERSON	QUOTE VALID	FREIGHT	DATE	TERMS - SPECIAL INSTRUCTIONS
TR	45 DAYS	PREPAID	11/08/10	NET30

QUANTITY	PART NUMBER	DESCRIPTION	INTERCHANGE	UNIT PRICE	AMOUNT
1	R012482	REPAIR		26795.40	26795.40
		REPAIRS TO FLYGT PROPELLER PUMP MODEL# 7050/680-5249			
		S/N 0680.000S0361041. TO INCLUDE THE FOLLOWING:			
		DISASSEMBLE, CLEAN, INSPECT, REPLACE BEARINGS,			
		SEALS, O-RINGS, T-BOARD, CABLE WASHERS, POWER CABLE,			
		GROMMETS, LOWER WEAR RING, OUTLET CONE, HARDWARE,			
		WELD & TURN SEAL AREAS, REPAIR OIL HOUSING, LOWER			
		BELL, HUB, COAT ENTIRE OUTSIDE OF PUMP, WASH & BAKE			
		STATOR, REASSEMBLE, TEST RUN, AND REFINISH.			
				Sub Total	26,795.40
				Tax	2,009.66
				S&H	
				Total	<b>28,805.06</b>
Accepted By: _____		Date: _____	Purchase Order# _____		

Thank You for the Opportunity to Quote Your Business  
[www.floridabearings.com](http://www.floridabearings.com)