

TEN-8 FIRE EQUIPMENT, INC

2904 59TH AVENUE DRIVE EAST
 BRADENTON FL 34203
 IN FLA: 1-800-228-8368
 PHONE: 941-756-7779
 FAX: 941-756-2598

141 MARITIME DRIVE
 SANFORD FL 32771
 PHONE: 407-328-5081
 FAX: 407-328-5083

visit us at: www.ten8fire.com

SALES ORDER

Order Number: SVT108975
 Order Date:
 Page: 3

Sold To: KEY WEST FIRE DEPT.
 mike/davila/305/809-3938
 1600 N. ROOSEVELT BLVD.
 KEY WEST, FL 33040

Ship To: KEY WEST FIRE DEPARTMENT
 mike/davila/305/809-3938
 1600 N ROOSEVELT BLVD
 KEY WEST, FL 33040

Ship Via
 Ship Date
 Terms NET 30 DAYS
 Work Done
 Problem CAB
 Equipment ENFORCER PUMPER
 Equipment ID 15735

Customer ID KEY W
 P.O. Number MIKE/DAVILA
 P.O. Date
 SalesPerson EAST
 Ten-8 Contact MICHAEL SWANN

Item No.	Description	UOM	Quantity	Unit Price	Total Price
	Transferred from page 2.....				472.97
	CORRECTION-REMOVE PRIMER PUMP ASSEMBLY.				
	REPLACE WITH A NEW PRIMER PUMP ASSEMBLY				
	THEN CHECK OPERATION.				
TECH4	POMPANO BEACH TECH	HOUR	3	98.00	294.00
WAT-9319	PRIMER PUMP SUB-ASSY. K-12.	EACH	1	1,409.20	1,409.20
FREIGHT	FREIGHT CHARGES	EACH	1	69.00	69.00

	SHOP SUPPLY FEE	EACH	1	73.12	73.12
	IMPORTANT NOTE: THIS TRUCK NEEDS TO COME TO				
	THE POMPANO SHOP FOR REPAIRS. THIS IS AN				
	ESTIMATE OF REPAIRS WE KNOW TO BE NEEDED				
	FROM				
	Transferred to page 4.....				2,318.29

TEN-8 FIRE EQUIPMENT, INC

2904 59TH AVENUE DRIVE EAST
BRADENTON FL 34203
IN FLA: 1-800-228-8368
PHONE: 941-756-7779
FAX: 941-756-2598

141 MARITIME DRIVE
SANFORD FL 32771
PHONE: 407-328-5081
FAX: 407-328-5083

visit us at: www.ten8fire.com

SALES ORDER

Order Number: SVT108975
Order Date:
Page: 4

Sold To: KEY WEST FIRE DEPT.
mike/davila/305/809-3938
1600 N. ROOSEVELT BLVD.
KEY WEST, FL 33040

Ship To: KEY WEST FIRE DEPARTMENT
mike/davila/305/809-3938
1600 N ROOSEVELT BLVD
KEY WEST, FL 33040

Ship Via
Ship Date
Terms NET 30 DAYS
Work Done
Problem CAB
Equipment ENFORCER PUMPER
Equipment ID 15735

Customer ID KEY W
P.O. Number MIKE/DAVILA
P.O. Date
SalesPerson EAST
Ten-8 Contact MICHAEL SWANN

Item No.	Description	UOM	Quantity	Unit Price	Total Price
----------	-------------	-----	----------	------------	-------------

	Transferred from page 3..... THE INITIAL INSPECTION PREFORMED WHILE WE WERE IN KEY WEST. ONCE WE BEGIN THE REPAIRS CURRENTLY SCHEDULED WE ARE SURE THERE WILL BE A NEED FOR ADDITIONAL PARTS AND LABOR. WHEN WE GET TO THAT POINT I WILL SUBMIT A SUPPLIMENTAL QUOTE FOR APPROVAL BEFORE PROCEEDING.				2,318.29
--	--	--	--	--	----------

I APPRECIATE YOUR BUSINESS.

Amount Subject to Sales Tax	0.00	Amount Exempt from Sales Tax	2,318.29	Subtotal:	2,318.29
				Invoice Discount:	0.00
				Sales Tax:	0.00
				Total:	2,318.29

TEN-8 FIRE EQUIPMENT, INC

2904 59TH AVENUE DRIVE EAST 141 MARITIME DRIVE
 BRADENTON FL 34203 SANFORD FL 32771
 IN FLA: 1-800-228-8368
 PHONE: 941-756-7779 PHONE: 407-328-5081
 FAX: 941-756-2598 FAX: 407-328-5083
visit us at: www.ten8fire.com

SALES ORDER

Order Number: SVT108971
 Order Date:
 Page: 2

Sold KEY WEST FIRE DEPT.
 To: MIKE/DAVILA/305809-3938
 1600 N. ROOSEVELT BLVD.
 KEY WEST, FL 33040

Ship KEY WEST FIRE DEPARTMENT
 To: MIKE/DAVILA/305809-3938
 1600 N ROOSEVELT BLVD
 KEY WEST, FL 33040

Ship Via
 Ship Date
 Terms NET 30 DAYS
 Work Done
 Problem
 Equipment DASH 2000 PUMPER
 Equipment ID 11391

Customer ID KEY W
 P.O. Number MIKE DAVILA
 P.O. Date
 SalesPerson EAST
 Ten-8 Contact MICHAEL SWANN

Item No.	Description	UOM	Quantity	Unit Price	Total Price
	Transferred from page 1..... CAUSE-NORMAL WARE.				115.32
	CORRECTION-REMOVE WORN VALVE ASSEMBLIES CLEAN INSPECT AND REBUILD.				
TECH4	POMPANO BEACH TECH	HOUR	4	98.00	392.00
AKR-8805	*CONVERSION 2" S/S BALL	EACH	2	82.24	164.48

COMPLAINT	3-OIL LEAKING AT THE ENGINE. CAUSE-VALVE COVER GASKETS ARE WORN AND THE OIL PAN GASKET IS WORN. CORRECTION-REMOVE THE VALVE COVERS AND CLEAN OFF THE OLD GASKET MATERIAL. REINSTALL THE VALVE				
	Transferred to page 3.....				671.80

TEN-8 FIRE EQUIPMENT, INC

2904 59TH AVENUE DRIVE EAST 141 MARITIME DRIVE
 BRADENTON FL 34203 SANFORD FL 32771
 IN FLA: 1-800-228-8368
 PHONE: 941-756-7779 PHONE: 407-328-5081
 FAX: 941-756-2598 FAX: 407-328-5083

visit us at: www.ten8fire.com

SALES ORDER

Order Number: SVT108971
 Order Date:
 Page: 4

Sold KEY WEST FIRE DEPT.
 To: MIKE/DAVILA/305809-3938
 1600 N. ROOSEVELT BLVD.
 KEY WEST, FL 33040

Ship KEY WEST FIRE DEPARTMENT
 To: MIKE/DAVILA/305809-3938
 1600 N ROOSEVELT BLVD
 KEY WEST, FL 33040

Ship Via
 Ship Date
 Terms NET 30 DAYS
 Work Done
 Problem
 Equipment DASH 2000 PUMPER
 Equipment ID 11391

Customer ID KEY W
 P.O. Number MIKE DAVILA
 P.O. Date
 SalesPerson EAST
 Ten-8 Contact MICHAEL SWANN

Item No.	Description	UOM	Quantity	Unit Price	Total Price
	Transferred from page 3..... CORRECTION-REMOVE DAMAGED MOULDING AND REPLACE WITH NEW MOULDING.				1,815.80
TECH4	POMPANO BEACH TECH	HOUR	2	98.00	196.00
PIE-930141	EXTR,RUBBER,WINDOW CHANNEL	FOOT	10	3.45	34.50
PIE-930170	@EXTRUSION RUBBER WINDOW TRIM	FOOT	6	2.40	14.40

	SHOP SUPPLY FEE		1	133.28	133.28
IMPORTANT NOTE: THIS TRUCK NEEDS TO COME UP TO					
	Transferred to page 5.....				2,193.98

TEN-8 FIRE EQUIPMENT, INC

2904 59TH AVENUE DRIVE EAST 141 MARITIME DRIVE
 BRADENTON FL 34203 SANFORD FL 32771
 IN FLA: 1-800-228-8368
 PHONE: 941-756-7779 PHONE: 407-328-5081
 FAX: 941-756-2598 FAX: 407-328-5083

visit us at: www.ten8fire.com

SALES ORDER

Order Number: SVT108971
 Order Date:
 Page: 5

Sold KEY WEST FIRE DEPT.
 To: MIKE/DAVILA/305809-3938
 1600 N. ROOSEVELT BLVD.
 KEY WEST, FL 33040

Ship KEY WEST FIRE DEPARTMENT
 To: MIKE/DAVILA/305809-3938
 1600 N ROOSEVELT BLVD
 KEY WEST, FL 33040

Ship Via
 Ship Date
 Terms NET 30 DAYS
 Work Done
 Problem
 Equipment DASH 2000 PUMPER
 Equipment ID 11391

Customer ID KEY W
 P.O. Number MIKE DAVILA
 P.O. Date
 SalesPerson EAST
 Ten-8 Contact MICHAEL SWANN

Item No.	Description	UOM	Quantity	Unit Price	Total Price
----------	-------------	-----	----------	------------	-------------

	Transferred from page 4..... POMPANO FOR REPAIRS. THIS IS AN ESTIMATE OF THE REPAIRS WE KNOW TO BE NEEDED FROM THE INITIAL INSPECTION PERFORMED WHILE WE WERE IN KEY WEST. ONCE WE START THE REPAIRS CURRENTLY SCHEDULED WE KNOW THERE WILL BE A NEED FOR ADDITIONAL PARTS AND LABOR. WHEN WE GET TO THAT POINT I WILL SUBMIT A SUPPLIMENTAL QUOTE FOR APPROVAL BEFORE PROCEEDING. I APPRECIATE YOUR BUSINESS				2,193.98
--	--	--	--	--	----------

Amount Subject to Sales Tax	0.00	Amount Exempt from Sales Tax	2,193.98	Subtotal:	2,193.98
				Invoice Discount:	0.00
				Sales Tax:	0.00
				Total:	2,193.98

TEN-8 FIRE EQUIPMENT, INC

2904 59TH AVENUE DRIVE EAST 141 MARITIME DRIVE
 BRADENTON FL 34203 SANFORD FL 32771
 IN FLA: 1-800-228-8368
 PHONE: 941-756-7779 PHONE: 407-328-5081
 FAX: 941-756-2598 FAX: 407-328-5083

visit us at: www.ten8fire.com

SALES ORDER

Order Number: SVT108973
 Order Date:
 Page: 1

Sold KEY WEST FIRE DEPT.
 To: MIKE/DAVILA/305/809-3938
 1600 N. ROOSEVELT BLVD.
 KEY WEST, FL 33040

Ship KEY WEST FIRE DEPARTMENT
 To: MIKE/DAVILA/305/809-3938
 1600 N ROOSEVELT BLVD
 KEY WEST, FL 33040

Ship Via
 Ship Date
 Terms NET 30 DAYS
 Work Done
 Problem STEERING GEAR BOX FAILURE
 Equipment VELOCITY PUMPER
 Equipment ID 20715

Customer ID KEY W
 P.O. Number MIKE/DAVILA
 P.O. Date
 SalesPerson EAST
 Ten-8 Contact MICHAEL SWANN

Item No.	Description	UOM	Quantity	Unit Price	Total Price
	MILES: HOURS:				
	KEY WEST ENGINE # 9				
COMPLAINT	1-STEERING BOX MOUNTING BOLTS ARE BACKING OUT. CAUSE-POSSIBLE THREADS BAD AT MOUNTING PLATE. CORRECTION-REMOVE STEERING BOXES TO INSPECT MOUNTING PLATE THREADS. REPLACE MOUNTING PLATE WITH A NEW PLATE ASSEMBLY.				
TECH4	POMPANO BEACH TECH	HOUR	21	98.00	2,058.00
TECH4	POMPANO BEACH TECH	HOUR	5	98.00	490.00
PIE-3408750	TRAY,STEERING GEAR WELDMENT TAK-4,PRGB	EACH	1	190.08	190.08
PIE-3865552	SPCR, 1.00X1.75X1.00 (962195)	EACH	3	6.50	19.50
PIE-82-0188-0002	BOLT .50"-13 CARR GR8 3.5"LONG (962195)	EACH	6	2.17	13.00
FREIGHT	FREIGHT CHARGES (962195)	EACH	6	153.75	922.50
	Transferred to page 2.....				3,693.08

TEN-8 FIRE EQUIPMENT, INC

2904 59TH AVENUE DRIVE EAST 141 MARITIME DRIVE
 BRADENTON FL 34203 SANFORD FL 32771
 IN FLA: 1-800-228-8368
 PHONE: 941-756-7779 PHONE: 407-328-5081
 FAX: 941-756-2598 FAX: 407-328-5083

visit us at: www.ten8fire.com

SALES ORDER

Order Number: SVT108973
 Order Date:
 Page: 2

Sold KEY WEST FIRE DEPT.
 To: MIKE/DAVILA/305/809-3938
 1600 N. ROOSEVELT BLVD.
 KEY WEST, FL 33040

Ship KEY WEST FIRE DEPARTMENT
 To: MIKE/DAVILA/305/809-3938
 1600 N ROOSEVELT BLVD
 KEY WEST, FL 33040

Ship Via
 Ship Date
 Terms NET 30 DAYS
 Work Done
 Problem STEERING GEAR BOX FAILURE
 Equipment VELOCITY PUMPER
 Equipment ID 20715

Customer ID KEY W
 P.O. Number MIKE/DAVILA
 P.O. Date
 SalesPerson EAST
 Ten-8 Contact MICHAEL SWANN

Item No.	Description	UOM	Quantity	Unit Price	Total Price
PIE-82-2018-0150	Transferred from page 1..... BOLT,.63-11UNC,HX FLNG,G8,PO (962246)	EACH	8	2.33	3,693.08 18.67
PIE-3401088	BLOCK,2X2X.5-.94 THRU-.38 CHAM TAK-4 (962246)	EACH	6	16.82	100.90

COMPLAINT	2-PRIMER PUMP DOES NOT OPERATE. CAUSE-PRIMER PUMP ASSEMBLY NEEDS TO BE REPLACED. CORRECTION-REMOVE BAD PRIMER PUMP ASSEMBLY. INSTALL NEW PRIMER PUMP ASSEMBLY AND TEST OPERATION.				
TECH4	POMPANO BEACH TECH	HOUR	3	98.00	294.00
WAT-9319	PRIMER PUMP SUB-ASSY. K-12.	EACH	1	1,409.20	1,409.20
FREIGHT	FREIGHT CHARGES	EACH	1	69.00	69.00
	SHOP SUPPLY FEE	EACH	1	227.36	227.36
	Transferred to page 3.....				5,812.21

