## Timeline of Events – 2320 Patterson Avenue

| March 4, 2021      | An exterior renovation permit application for BLD2021-0584 was submitted to the Building                    |
|--------------------|---|
| 1010111,2022       | Department for 2320 Patterson Avenue by Gulfstream Construction.  |
| May 5, 2021        | A code violation, Code Case CC2021-00760, was opened for unpermitted site work.                             |
| May 20, 2021       | A site visit was conducted by the Floodplain Manager. The site visit revealed the permit                    |
| , ,                | application for BLD2021-0584 was undervalued. Applicant was advised a cost breakdown, as-is                 |
|                    | private appraisal, and updated plans must be submitted.   |
| June 2, 2021       | Mark Passero contacted the Code Compliance Department about the status of the building                      |
|                    | permit application.   |
| June 11, 2021      | A private appraisal, schedule of values, and updated plans were submitted for building permit BLD2021-0584. |
| June 14, 2021      | The private appraisal and schedule of values were not accepted by the Floodplain Manager.                   |
| July 16, 2021      | BLD2021-0584 is still in corrections with the Floodplain Manager due to concerns with the                   |
|                    | submitted private appraisal and schedule of values; property owner Mark Passero met with the                |
|                    | CBO, Raj Ramsingh and Code Officer Troy Montero.  |
| July 26, 2021      | Gulfstream Construction applied for a building permit for after-the-fact exploratory demolition.            |
|                    | The permit, BLD2021-2179, was intended to satisfy the unpermitted work cited in CC2021-                     |
|                    | 00760.  |
| August 10, 2021    | BLD2021-2179 was approved for the after-the-fact exploratory demolition associated with                     |
|                    | CC2021-00760 under the condition that no further work is conducted, and the permit is closed                |
|                    | once paid for and issued.   |
| February 11, 2022  | BLD2021-0584 approved with the following conditions:  |
|                    | 1. The City conducts all inspections on the property.   |
|                    | 2. All work adheres to the submitted schedule of value using the specified type of                          |
|                    | finishes.   |
|                    | 3. The garage is not converted into habitable space.  |
|                    | 4. The footprint of the existing house remains the same.  |
|                    | 5. No additions or expansions to any walls shall occur.   |
| March 3, 2022      | Subsequent roofing permit, BLD2022-0616, is applied for and approved.                                       |
| April 13, 2022     | Subsequent plumbing permit, BLD2022-1053 approved.  |
| April 26, 2022     | Subsequent mechanical HVAC permit, BLD2022-0722, approved on the condition that the A/C                     |
|                    | units are mounted above BFE=1' and outside of the required setbacks.  |
| April 27, 2022     | Subsequent electrical permit, BLD2022-0725, approved.   |
| November 30, 2022  | Building inspections for permits BLD2022-1053 (plumbing by Inspector Wright) and BLD2022-                   |
|                    | 0725 (electrical/mechanical inspection by Inspector Richardson) were disapproved. Both                      |
|                    | inspectors expressed concerns with the provided job valuation.  |
| January 10, 2023   | Building inspection for permit BLD2022-0722 is disapproved by Inspector Richardson and CFM                  |
|                    | Bridget Flores due to the condenser unit not being elevated at or above BFE+1'.                             |
| September 13, 2023 | Site visit with Mark Passero, Bart Smith (Passero's representative), Raj Ramsingh, and Zoe                  |
|                    | Porter (CFM for the City). The site visit exhibited additional work that was not approved via               |
|                    | BLD2021-0584, as well as the use of unapproved materials.   |