

Karen Olson

From: Bobby Brown <BBrown@ebsaryfoundationco.com>
Sent: Monday, April 20, 2020 8:54 AM
To: Karen Olson; Doug Bradshaw
Cc: Francisco Quintero
Subject: Dock Damage Survey
Attachments: IMG_1045.JPG; IMG_1044.JPG; IMG_1049.JPG; IMG_1052.JPG; IMG_1048.JPG; IMG_1047.JPG

Karen, Doug,

My preliminary results below for my survey of Docks A and C. A-Dock from harbor walk out not including previously repaired fingers. C-dock including fuel pier and around building.

Attached representative photos. A lot of the rusting/swelling hardware has caused cracking in the structural timbers. I included timbers on this list that showed enough damage that the overall deck appears to have settled out of the originally constructed elevation or otherwise appear close to failure.

A dock Bad pile – 11 Each

A dock Cracked Stringer/Joist – 8 Each

A dock Missing Diagonal 1 Each, but additional bracing should be added to A-dock fingers mid span to reduce movement.

C dock Bad Pile – 4 Each

C dock Cracked stringer/Joist – 8 Each

This is not a survey of every structural component and meant to be representative of the area described.

Regards,

Bobby Brown
Estimator



2154 Northwest North River Drive

Miami, Florida 33125

Phone: (305) 439-9280

Fax: (305) 325-8684

Email: BBrown@ebsaryfoundationco.com

Website: www.ebsaryfoundationco.com

Confidentiality Note: This message (including any attachments) is intended for use only by the individual or entity to which it is addressed and may contain information that is privileged, confidential, and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering the message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please contact the sender immediately and destroy the material in its entirety, whether electronic or hard copy. Thank you.