






P60

P61

P63

P62




P54

P?60A

P60

P61







Tree #52 (existing building to be demolished, new structure to be built)

P52 (one rootball-4 trunks)






P47




P47



P40

P39

P38



P35

No impacts proposed for this area





P42



49, P32

48, P31







No impacts to occur to
vegetation along this area.







P23




Area containing
19-29 in a canopy
dominated by
Brazilian Pepper

P22



Area containing tree 13-18 under a canopy dominated by Brazilian Pepper



Trees 10, 11, 12



Old stormwater
ditching





10



Area containing trees #8-area
dominated by Brazilian pepper



No impacts to occur to trees in this parking lot area.




No impacts to occur to the trees in this parking lot area.













P5

