




Stewart & Stevenson FDDA LLC, DBA. Florida Detroit Diesel Allison- Miami MV-90099

2277 NW 14th Street Miami, Florida 33125
 Phone: (305) 638-5300



Case Number: 14864880
Repair Order Number: MIA549091
Purchase Order Number: N/A
Service Advisor: Milton, Douglas - Case Date 2024-02-29 14:27:17 -0500

Customer: City Of Key West	Unit Number: 829	
Address: 5701 COLLEGE ROAD KEY WEST, FL 33040 Phone: (305) 809-3911 Fax: N/A Customer Number: 66372	Asset: 2018 GILLIG LOW FLOOR [LOW FLOOR] Serial Number: J3093362 VIN: 15GGE3019J3093362 Engine: Not Supported	

Case Complaint: QUOTE TO DIAGNOSE UNIT
 UNIT WILL NOT START PESSABLE ESS OR DIPIM
 S/N 7110009337

Item	Operation Name	Hourly Rate	Totals
1	DIAGNOSE UNIT FOUND THE VANNER AND FUSE SHORTED REPLACE THE VANNER AND FUSE AND PROGRAM THE SYSTEM AND ROAD TEST		
	Labor:	\$6,150.00	\$6,150.00
	Parts:		\$8,264.78
	-(1.0) [ADJUST] ADJUST		
2	AFTER TESTING THE SYS FOUND THE ESS LEAKING INTERNALLY NEED TO REPLACE THE ESS AND PROGRAM THE SYSTEM		
	Labor:	\$4,920.00	\$4,920.00
	Parts:		\$93,136.23
	-(1.0) [ADJUST] ADJUST		
		Parts:	\$101,401.01
		Labor:	\$11,070.00
		Total:	\$112,471.01

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employee's permission to operate the vehicle or engine herein described on streets, highways or elsewhere for the purpose of testing and/or inspection if required. An express mechanic's lien is hereby acknowledged on the above vehicle or engine to secure the amount of repairs thereto. Repairer is not responsible for the loss or damage to articles left with or in the vehicle or engine in case of fire, theft or any other cause beyond its control. Estimate good for 30 days

Standard Terms and Conditions are included herein by reference and available at: <https://www.stewartandstevenson.com/terms-of-sale/> (click address to view)

AUTHORIZED BY: _____ DATE: ___/___/___
 Other Authorized Person _____

 **Stewart & Stevenson FDDA LLC, DBA. Florida Detroit Diesel Allison- Miami I**

Customer: City Of Key West

Unit Number: 829

Case Number: 14864880

Asset: 2018 GILLIG LOW FLOOR [LOW FLOOR]

VIN: 15GGE3019J3093362



I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED \$100.
_____ I REQUEST A WRITTEN ESTIMATE.

_____ I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$ _____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.

_____ I DO NOT REQUEST A WRITTEN ESTIMATE.

SIGNED _____ DATE _____

Customer' Intended Payment Method CASH CREDIT CARD CHECK FINANCE

Hazardous waste charge represents costs and profits to the motor vehicle repair facility for Miscellaneous Shop Supplies or Waste Disposal and other Fees. FS403.718 mandates a \$1.00 fee for each new tire sold in the State of Florida. FS403.7185 mandates a \$1.50 fee for each new or remanufactured battery sold in the State of Florida.

Minimum Diagnosis Fee 2 labor hours.

STORAGE FEES. Fee of \$100 per day may be charged if equipment is left more than 3 days after notification of completion.

Proposed Completion Date: _____

Save Old Parts: Yes No (Core may apply)

Warranties: Labor 90 days / New Parts 1 year / Mileage Unlimited. Unless otherwise stated.