



## Legislation Details

**File #:** 18-2438      **Version:** 1      **Name:**  
**Type:** Code Violations      **Status:** Passed  
**File created:** 6/8/2018      **In control:** Code Compliance Hearing  
**On agenda:** 6/27/2018      **Final action:** 6/27/2018  
**Title:** Case # 18-247  
Juan Betancurt  
291 Front St  
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
Sec. 14-262 Request for inspection  
Officer Wherden Charles  
Certified Service: 5-19-2018  
Initial Hearing: 6-27-2018

New Case

Count 1: Failure to obtain an electrical permit for the placement of LED lights on the ceiling. Count 2: Failure to obtain an electrical inspection.

**Sponsors:**

**Indexes:**

**Code sections:**

**Attachments:**

Date	Ver.	Action By	Action	Result
6/27/2018	1	Code Compliance Hearing	Violation Fine	