



## Legislation Details (With Text)

<b>File #:</b>	18-2767	<b>Version:</b>	1	<b>Name:</b>	
<b>Type:</b>	Code Violations	<b>Status:</b>	Passed		
<b>File created:</b>	8/14/2018	<b>In control:</b>	Code Compliance Hearing		
<b>On agenda:</b>	9/26/2018	<b>Final action:</b>	10/31/2018		
<b>Title:</b>	Case # 18-785 Eithne Dunne John Dunne Josephine Dunne 1506 Rose Street Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions Sec. 14-262 Request for inspection Officer Jorge Lopez Certified Service: 9-21-2018 Initial Hearing: 9-26-2018  In compliance 24 Oct 2018; Request dismissal  Count 1: Electrical outlets and sliding glass doors installed without permits. Count 2: Failure to obtain electrical inspection.				

### Sponsors:

### Indexes:

### Code sections:

### Attachments:

Date	Ver.	Action By	Action	Result
10/31/2018	1	Code Compliance Hearing	Dismissed	
9/26/2018	1	Code Compliance Hearing	Continuance	

### Case # 18-785

Eithne Dunne  
John Dunne  
Josephine Dunne  
1506 Rose Street  
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
Sec. 14-262 Request for inspection  
Officer Jorge Lopez  
Certified Service: 9-21-2018  
Initial Hearing: 9-26-2018

### In compliance 24 Oct 2018; Request dismissal

**Count 1:** Electrical outlets and sliding glass doors installed without permits. **Count 2:** Failure to obtain electrical inspection.