

City of Key West, FL

City Hall 1300 White Street Key West FL 33040

Legislation Details (With Text)

File #: 21-6809 Version: 1 Name:

Type: Action Items Status: Passed

File created: 3/15/2021 In control: Contractors Examining Board

On agenda: 4/7/2021 Final action: 4/7/2021

Title: HEARING:

Case #21-0583

Contractor: Frank White, Key West Boyz Co., Inc.

Inspector: Troy Montero

Date of Violation(s) 11/05/2020

Code Violations

Count 1: Sec. 14-37 -Building without a permit

Address: 1617 White St, Key West, Fl.

Permit: 21-0583 Code Case #20-01335

On 11/05/2020 the City of Key West Code Compliance Department received an anonymous complaint regarding work without the benefit of required permitting. Code Officer Troy Montero responded to the complaint and found a complete accessory structure being constructed without the benefit of a

building permit.

Count 2: F.S. 489.113 (2) (a) & (b)

Officer Montero photographed a sewage grinder pump and plumbing lines being installed without the

benefit of a plumbing permit. Mr. White is not licensed to perform plumbing.

Sponsors:

Indexes:

Code sections:

Attachments: 1. Cert. Mail & Lt., 2. Photos 20-01335, 3. Case Details update, 4. 21-

0583AccessoryStructurePermitDetails, 5. 21-00849PlumbingPermitDetails, 6. 21-

0910ElectricPermitDetails, 7. CodeNotice

DateVer.Action ByActionResult4/7/20211Contractors Examining BoardApprovedPass

HEARING:

Case #21-0583

Contractor: Frank White, Key West Boyz Co., Inc.

Inspector: Troy Montero

Date of Violation(s) 11/05/2020

Code Violations

Count 1: Sec. 14-37 -Building without a permit

File #: 21-6809, Version: 1

Address: 1617 White St, Key West, Fl.

Permit: 21-0583

Code Case #20-01335

On 11/05/2020 the City of Key West Code Compliance Department received an anonymous complaint regarding work without the benefit of required permitting. Code Officer Troy Montero responded to the complaint and found a complete accessory structure being constructed without the benefit of a building permit.

Count 2: F.S. 489.113 (2) (a) & (b)

Officer Montero photographed a sewage grinder pump and plumbing lines being installed without the benefit of a plumbing permit. Mr. White is not licensed to perform plumbing.

Sponsors: Mr. Justice

Attachments: