



Shed #1 on right and Shed #2 on left behind fence & under tree Photo #2



#3 - Locked gate leading to courtyard between sheds. Only access to shed #1.



Photo #4 – Mailbox between gate to shed #1 and entrance door to shed #2



Photo #5 – Shed #2 PVC pipe between shed & neighbor building – Photo #6 - close up of unpermitted plumbing PVC pipe



Photo #7 - Orange extension cord for electric to shed #2 on temporary electric pole



Photo #8 - Unpermitted plumbing work under shed #2 – left side of entrance door



Photo #9 - Right side of entrance door under shed #2



Photo #10 - Underside of 2nd shed with cable and orange extension cord for electric leading from temp pole

