

# PHOTOS

CASE #11-1233

3601 NORTHSIDE DR.



Kitchen Demolished and Renovated without bldg. permits.



Electrical wiring installed in kitchen, bedroom, and outside flood lights without permits, by Vincent, an unlicensed contractor.

# PHOTOS

CASE #11-1233

3601 NORTHSIDE DR.



Bathroom demolished without building permit.



Concrete floor poured without building permits, per current tenant.

Photos by Dottie Austin, Oct. 11, 2011