

Tree Values Report

Glenn Archer City Hall Complete Tree List (February 2014)

TREE ID	Species	DBH	Species value	Location Value	Condition Value	City KW Tree Value	Replacement Value	Recommendation	Comment
1	Royal Poinciana	15"	100%	50%	30%	60%	9"	REMOVE	Tree at Seminary and White St, poor condition (hollow and rot), very visual tree, sidewalk and road issues with roots, powerlines -TC
2	Queen Palm						1-Native Palm	REMOVE	Tree along White St- Staff permit
3	Queen Palm						1-Native Palm	REMOVE	Tree along White St- Staff permit
4	Alexander Palm						1-Native Palm	REMOVE	Tree along White St- Staff permit
5	Bottlebush	6"	50%	70%	50%	56%	3.4"	REMOVE	Tree along White St, poor structural condition (base of trunk)-TC
6	Bottlebush	6"	50%	70%	50%	56%	3.4"	REMOVE	Tree along White St, poor structural condition -TC
7	Alexander Palm						1-Native Palm	REMOVE	Tree along White St- Staff permit
8	Queen Palm						1-Native Palm	REMOVE	Tree along White St- Staff permit
9	Queen Palm						1-Native Palm	REMOVE	Tree along White St- Staff permit
9a	Queen Palm						NPR	REMOVE	Tree along White St- no permit required, <10ft tall
10	Alexander Palm						1-Native Palm	REMOVE	Tree along White St- Staff permit
11	Mahogany	30"	100%	80%	80%	87%	NA	REMAIN	Tree located near corner of White St on United-Nice tree
12	Sabal Palm		native				NA	REMAIN	Tree on United Close to White St intersection-REMAIN
13	NO TREE								
14	Sea Grape	6"	100%	50%	40%	63%	3.8"	REMOVE	tree at United St, poor condition, close to building-TC
14a	Thatch Palm		native				NA	TRANSPLANT	Tree along United St-Staff permit
15	Alexander Palm						NPR	REMOVE	NPR <10 ft tall
16	Alexander Palm						1-Native Palm	REMOVE	Tree along United St- Staff permit
16a	Alexander Palm						1-Native Palm	REMOVE	Tree along United St- Staff permit
16b	Alexander Palm						1-Native Palm	REMOVE	Tree along United St- Staff permit
16c	Alexander Palm						NPR	REMOVE	NPR <10 ft tall
16d	Alexander Palm						NPR	REMOVE	NPR <10 ft tall

NOTE: There is no tree # 13 or #51

Glenn Archer City Hall Complete Tree List (February 2014)

TREE ID	Species	DBH	Species value	Location Value	Condition Value	City KW Tree Value	Replacement Value	Recommendation	Comment
17	Gumbo Limbo	12"	100%	80%	80%	87%	NA	REMAIN	Tree along United St
18	Royal Poinciana	24"	100%	70%	30%	66%	15.8"	REMOVE	Tree along United St, double trunk, has a large rot section mid trunk, poor conition, structural a potential hazard
19	Gumbo Limbo	10"	100%	50%	40%	63%	6.3"	REMOVE	Tree along United St, poor structural shape-main trunk leader growing to one side over road, very close to existing sidewalk and roots uplifting sidewalk-TC
20	Sabal Palm		native				NA	TRANSPLANT	Tree along United St-Staff permit
21	Sabal Palm		native				NA	TRANSPLANT	Tree along United St-Staff permit
22	Sabal Palm		native				NA	TRANSPLANT	Tree along United St-Staff permit
23	Sabal Palm		native				NA	TRANSPLANT	Tree along United St-Staff permit
24	Sabal Palm		native				NA	TRANSPLANT	Tree along United St-Staff permit
25	Sabal Palm		native				NA	REMAIN	Tree along United St
26	Sabal Palm		native				NA	REMAIN	Tree along United St
27	Schefflera/Umbrella	24"	0%	0%	0%	0%	NPR	REMOVE	NPR
28	Sabal Palm		native				NA	REMAIN	Tree along United St
29	Sabal Palm		native				NA	REMAIN	Tree along United St
30	Sabal Palm		native				NA	REMAIN	Tree along United St
31	Sabal Palm		native				NA	TRANSPLANT	Tree along United St-Staff permit
32	Sabal Palm		native				NA	REMAIN	Tree along United St
33	Sabal Palm		native				NA	REMAIN	Tree along United St
34	Sabal Palm		native				NA	REMAIN	Tree along United St
35	Sabal Palm		native				NA	REMAIN	Tree along United St
36	Sabal Palm		native				NA	REMAIN	Tree along United St
37	Coconut Palm						NA	TRANSPLANT	Tree along United St-Staff permit
38	Coconut Palm						NA	TRANSPLANT	Tree along United St-Staff permit
39	Coconut Palm						NA	TRANSPLANT	Tree along United St-Staff permit
40	Sabal Palm		native				NA	REMAIN	Tree along United St
41	Sabal Palm		native				NA	REMAIN	Tree along United St
42	Sabal Palm		native				NA	TRANSPLANT	Tree along United St-Staff permit

NOTE: There is no tree # 13 or #51

Glenn Archer City Hall Complete Tree List (February 2014)

TREE ID	Species	DBH	Species value	Location Value	Condition Value	City KW Tree Value	Replacement Value	Recommendation	Comment
42a	Sabal Palm		<i>native</i>				NA	TRANSPLANT	Tree along United St-Staff permit
43	Sabal Palm		<i>native</i>				NA	TRANSPLANT	Tree along United St-Staff permit
44	Sabal Palm		<i>native</i>				NA	TRANSPLANT	Tree along United St-Staff permit
45	Strangler Fig		100%	80%	80%	87%	NA	REMAIN	Large tree along Grinnell St
45a	Alexander Palm						1-Native Palm	REMOVE	Tree along Grinnell St-Staff permit
46	Royal Poinciana	25"	100%	50%	60%	70%	17.5"	REMOVE	Tree along Seminary St, power lines and transformer issues, sidewalk issues, numerous poor cuts in canopy, overall fair condition-TC
47	Sandbox	26"	50%	50%	30%	43%	11"	REMOVE	Tree along Seminary St, power lines and sidewalk issues, numerous poor cuts in canopy, overall very poor condition-TC
48	Sandbox	17"	50%	50%	30%	43%	7.3"	REMOVE	Tree along Seminary St, poor condition and structure, lots of decay-autograph tree growing in crotch-TC
49	Sandbox	19"	50%	50%	60%	53%	NA	REMAIN ?	Tree along Seminary St old scar at trunk base, structure and health fair
50	Sandbox	28"	50%	40%	40%	43%	12"	REMOVE	Tree along Seminary St, has fungus and decay, in transformer and utility lines, sidewalk impacts-TC
51	NO TREE								
52	Jamaican Dogwood	8"	100%	70%	70%	80%	NA	REMAIN	Tree along Seminary St, fair condition.
53	Jamaican Dogwood	12"	100%	40%	50%	63%	7.5"	REMOVE	Tree along Seminary St, poor structure, major root issues-TC
54	Alexander Palm						1-Native Palm	REMOVE	Tree along White St-Staff permit
55	Alexander Palm						1-Native Palm	REMOVE	Tree along White St-Staff permit
56	Silver Buttonwood	8"	100%	80%	60%	80%	6.4"	REMOVE	Tree along White St, crowding, fair health-TC
56a	Desert Cassia	8.5"	50%	80%	70%	66%	5.6"	REMOVE	Tree along White St, crowding, fair health-TC

NOTE: There is no tree # 13 or #51

Glenn Archer City Hall Complete Tree List (February 2014)

TREE ID	Species	DBH	Species value	Location Value	Condition Value	City KW Tree Value	Replacement Value	Recommendation	Comment
56b	Red Cedar	2.5"	50%				NPR	REMOVE	NPR <4" dsh
56c	Red Cedar	2.5"	50%				NPR	REMOVE	NPR <4" dsh
57	Lignum vitae		100%	90%	100%	97%	NA	REMAIN	Tree along White St
58	Lignum vitae		100%	90%	100%	97%	NA	REMAIN	Tree along White St
59	Desert Cassia	5"	50%	80%	70%	66%	3.3"	REMOVE	Tree along White St, crowding, fair health-TC
60	Red Cedar	1"	50%				NPR	REMOVE	NPR <4" dsh
61	Sabal Palm		<i>native</i>				1-Native Palm	REMOVE	Tree along Seminary St-Staff permit