



Legislation Details (With Text)

File #: 18-2438 **Version:** 1 **Name:**

Type: Code Violations **Status:** Passed

File created: 6/8/2018 **In control:** Code Enforcement Hearing

On agenda: 6/27/2018 **Final action:** 6/27/2018

Title: Case # 18-247
 Juan Betancurt
 291 Front St
 Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions
 Sec. 14-262 Request for inspection
 Officer Wherden Charles
 Certified Service: 5-19-2018
 Initial Hearing: 6-27-2018

New Case

Count 1: Failure to obtain an electrical permit for the placement of LED lights on the ceiling. Count 2: Failure to obtain an electrical inspection.

Sponsors:

Indexes:

Code sections:

Attachments:

Date	Ver.	Action By	Action	Result
6/27/2018	1	Code Enforcement Hearing	Violation Fine	

Case # 18-247

Juan Betancurt
 291 Front St
 Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions
 Sec. 14-262 Request for inspection
 Officer Wherden Charles
 Certified Service: 5-19-2018
 Initial Hearing: 6-27-2018

New Case

Count 1: Failure to obtain an electrical permit for the placement of LED lights on the ceiling. **Count 2:** Failure to obtain an electrical inspection.