

# City of Key West, FL

City Hall 1300 White Street Key West FL 33040

## Legislation Details (With Text)

File #: 2017-1064 Version: 1 Name:

Type: Code Violations Status: Passed

File created: 8/3/2017 In control: Code Compliance Hearing

On agenda: 8/30/2017 Final action: 6/27/2018

**Title:** Case # 16-335

Eleanor J Miller-Laino 3735 Cindy Avenue

Sec. 90-363 Certificate of occupancy - Required Sec. 58-61 Determination and levy of charge Sec. 122-238 Dimensional requirements

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Officer Jorge Lopez

Certified Service: 7-17-2017 Initial Hearing: 8-30-2017

In compliance 31 May 2018; request case to be closed

Count 1: Failure to obtain a certificate of occupancy. Count 2: Failure to pay impact fees related to utilities. Count 3: This unit/structure is located in the rear side of the subject property in the setback. Count 4: Renovations including plumbing and electrical work done without the benefit of building

permits.

Sponsors: Indexes:

Code sections:

#### Attachments:

| Date       | Ver. | Action By               | Action      | Result |
|------------|------|-------------------------|-------------|--------|
| 6/27/2018  | 1    | Code Compliance Hearing | Dismissed   |        |
| 4/25/2018  | 1    | Code Compliance Hearing | Continuance |        |
| 1/31/2018  | 1    | Code Compliance Hearing | Continuance |        |
| 12/20/2017 | 1    | Code Compliance Hearing | Continuance |        |
| 8/30/2017  | 1    | Code Compliance Hearing | Continuance |        |

#### Case # 16-335

Eleanor J Miller-Laino 3735 Cindy Avenue

Sec. 90-363 Certificate of occupancy - Required Sec. 58-61 Determination and levy of charge Sec. 122-238 Dimensional requirements

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Officer Jorge Lopez

Certified Service: 7-17-2017 Initial Hearing: 8-30-2017 File #: 2017-1064, Version: 1

### In compliance 31 May 2018; request case to be closed

**Count 1:** Failure to obtain a certificate of occupancy. **Count 2:** Failure to pay impact fees related to utilities. **Count 3:** This unit/structure is located in the rear side of the subject property in the setback. **Count 4:** Renovations including plumbing and electrical work done without the benefit of building permits.