



Legislation Details (With Text)

**File #:** 18-2455      **Version:** 1      **Name:**  
**Type:** Code Violations      **Status:** Passed  
**File created:** 6/8/2018      **In control:** Code Enforcement Hearing  
**On agenda:** 6/27/2018      **Final action:** 11/28/2018  
**Title:** Case # 18-675  
Victor & Cynthia Mills  
1202 White Street  
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
Sec. 14-325 Permit required - Dismissed  
Sec. 14-262 Request for inspection - Dismissed  
Officer Jorge Lopez  
Certified Service: 6-6-2018  
Initial Hearing: 6-27-2018

In compliance 27 Nov 2018; Request dismissal

Count 1: Failure to obtain all required permits for drywall work and ceiling work. Count 2: Failure to obtain mechanical permits for the HVAC system installation. - Dismissed Count 3: Failure to obtain all required inspections. - Dismissed

**Sponsors:**

**Indexes:**

**Code sections:**

**Attachments:**

| Date       | Ver. | Action By                | Action      | Result |
|------------|------|--------------------------|-------------|--------|
| 11/28/2018 | 1    | Code Enforcement Hearing | Dismissed   |        |
| 10/31/2018 | 1    | Code Enforcement Hearing | Continuance |        |
| 9/26/2018  | 1    | Code Enforcement Hearing | Continuance |        |
| 6/27/2018  | 1    | Code Enforcement Hearing | Continuance |        |

**Case # 18-675**

Victor & Cynthia Mills  
1202 White Street  
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
~~Sec. 14-325 Permit required - Dismissed~~  
~~Sec. 14-262 Request for inspection - Dismissed~~  
Officer Jorge Lopez  
Certified Service: 6-6-2018  
Initial Hearing: 6-27-2018

**In compliance 27 Nov 2018; Request dismissal**

~~Count 1: Failure to obtain all required permits for drywall work and ceiling work. Count 2: Failure to obtain mechanical permits for the HVAC system installation. - Dismissed Count 3: Failure to obtain~~

all required inspections. - Dismissed