



Legislation Details (With Text)

**File #:** 13-4544      **Version:** 1      **Name:**  
**Type:** Code Violations      **Status:** Passed  
**File created:** 7/8/2013      **In control:** Code Compliance Hearing  
**On agenda:** 7/31/2013      **Final action:** 10/30/2013  
**Title:** Case # 13-511  
Kevin & Yvette Talbott  
1701 Johnson Street  
Sec. 14-37 Building permits, professional plans; display of permits  
Sec. 66-87 Business tax receipt for all holding themselves out to be engaged in business  
Sec. 90-363 Certificate of occupancy - Required  
Sec. 58-61 Determination and levy of change  
Officer Peg Corbett  
Certified Service: 7-8-2013  
Initial Hearing: 7-31-2013

Continued from August 28, 2013 for compliance

Count 1: A complaint was received that the garage was enclosed. Site visit confirmed that it was enclosed and a door and two windows were also installed. A fence was built on either side with a gate entry from the Ashby Street side all without benefit of a building permit. Count 2: A business tax receipt is required to rent this property. Count 3: A certificate of occupancy is required to rent this property. Count 4: The subject property does not have the required utility accounts or a waste management account as required by the city.

**Sponsors:**

**Indexes:**

**Code sections:**

**Attachments:** 1. 13-511 1701 Johnson NOH 5491, 2. 13-511 1701 Johnson St Photos of illegal unit, 3. 13-511 Naviline view shows one legal unit

Date	Ver.	Action By	Action	Result
10/30/2013	1	Code Compliance Hearing	Violation Fine	
8/28/2013	1	Code Compliance Hearing	Continuance	
7/31/2013	1	Code Compliance Hearing	Continuance	

**Case # 13-511**

Kevin & Yvette Talbott  
1701 Johnson Street  
Sec. 14-37 Building permits, professional plans; display of permits  
Sec. 66-87 Business tax receipt for all holding themselves out to be engaged in business  
Sec. 90-363 Certificate of occupancy - Required  
Sec. 58-61 Determination and levy of change  
Officer Peg Corbett  
Certified Service: 7-8-2013  
Initial Hearing: 7-31-2013

**Continued from August 28, 2013 for compliance**

**Count 1:** A complaint was received that the garage was enclosed. Site visit confirmed that it was enclosed and a door and two windows were also installed. A fence was built on either side with a gate entry from the Ashby Street side all without benefit of a building permit. **Count 2:** A business tax receipt is required to rent this property. **Count 3:** A certificate of occupancy is required to rent this property. **Count 4:** The subject property does not have the required utility accounts or a waste management account as required by the city.