



## Legislation Text

File #: 18-3323, Version: 1

### Case # 18-1904

S Group Inc - **Counts 1 & 2 only**

Andrienne Sanchez - Registered Agent - **Counts 1 & 2 only**

Richard & Deborah Pesce - Property Owners - **Counts 1 thru 10 and 12 only**

Michael Herrera - **Counts 1 thru 10 and 12 thru 13 with Repeat Count 11.**

712 Eaton Street

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-40 Permits in historic districts

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-261 Failure to obtain

Sec. 14-327 Inspection

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-40 Permits in historic districts

Sec. 18-150 Certificate of competency required

Sec. 18-117 Acts declared unlawful

Sec. 66-87 Business tax receipt required for all holding themselves out to be engaged in business

Officer Jorge Lopez

Certified Mail: 12-13-2018 - Registered Agent (Amended Notice)

Certified Mail: 12-18-2018 - Richard & Deborah Pesce (Amended Notice)

Posted: 1-7-2019 - Michael Herrea

Initial Hearing: 1-30-2019

### Settlement Agreement

**Count 1:** Failure to obtain the permit for the exterior renovations regarding the railings and column.

**Count 2:** Failure to obtain the certificate of appropriateness for the railings on the second floor and one column removal on the first floor. **Count 3:** Electrical work performed without the benefit of an electrical permit. **Count 4:** Failure to obtain an electrical permit. **Count 5:** Failure to obtain an electrical inspection. **Count 6:** Plumbing work performed without the benefit of a plumbing permit.

**Count 7:** Installation of new kitchen cabinets without the benefit of permits. **Count 8:** Framing and plumbing work performed without the benefit of permits. **Count 9:** New structure being built in the rear side of the property without the benefit of a permit. **Count 10:** New structure being built without the benefit of a certificate of appropriateness. **Count 11:** Does not have a certificate of competency to operate as a licensed electric contractor nor a licensed plumbing contractor. Mr. Herrera was found in violation in Case# 17-1019. **Count 12:** Unlawful for work to be performed by an unlicensed contractor. **Count 13:** Failure to obtain a business tax receipt which is required.

