



Legislation Details (With Text)

File #: 19-3773 **Version:** 1 **Name:**
Type: Code Violations **Status:** Passed
File created: 3/20/2019 **In control:** Code Compliance Hearing
On agenda: 4/24/2019 **Final action:** 6/27/2019
Title: Case # 19-253
Poinciana Park Partners, LLP - Mobile Home Park Owner
Erwin & Didier M. Mayer
Evelyne Cajuste & Pierre Louis - Mobile Home Owner
1300 15th Court Lot 45
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions
Sec. 14-262 Request for inspection
Director Jim Young
Posted: 4-26-2019 - Mobile Home Owner
Posted: 4-26-2019 - Mobile Home Park
Initial Hearing: 4-24-2019

In compliance 19 June 2019; Request dismissal

Count 1: Failure to obtain building permits for the structure built in the rear side of the mobile home.
Count 2: Failure to obtain an electrical permit for the enclosed structure. Count 3: Failure to obtain the required electrical inspection.

Sponsors:

Indexes:

Code sections:

Attachments:

Date	Ver.	Action By	Action	Result
6/27/2019	1	Code Compliance Hearing	Dismissed	
5/29/2019	1	Code Compliance Hearing	Continuance	
4/24/2019	1	Code Compliance Hearing	Continuance	

Case # 19-253

Poinciana Park Partners, LLP - Mobile Home Park Owner

Erwin & Didier M. Mayer

Evelyne Cajuste & Pierre Louis - Mobile Home Owner

1300 15th Court Lot 45

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-262 Request for inspection

Director Jim Young

Posted: 4-26-2019 - Mobile Home Owner

Posted: 4-26-2019 - Mobile Home Park

Initial Hearing: 4-24-2019

In compliance 19 June 2019; Request dismissal

Count 1: Failure to obtain building permits for the structure built in the rear side of the mobile home.

Count 2: Failure to obtain an electrical permit for the enclosed structure. **Count 3:** Failure to obtain the required electrical inspection.