



## Legislation Details (With Text)

**File #:** 19-4628      **Version:** 1      **Name:**  
**Type:** Code Violations      **Status:** Passed  
**File created:** 8/20/2019      **In control:** Code Compliance Hearing  
**On agenda:** 10/30/2019      **Final action:** 10/30/2019  
**Title:** Case # 19-463  
G. B & B-B Registries, LLC  
210 Simonton Street Lot  
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
Sec. 14-40 Permits in historic districts  
Sec. 14-262 Request for inspection  
Officer Dorian Patton  
Certified Mail: 8-9-2019  
Initial Hearing: 9-25-2019

Continued from 25 Sept 2019

Count 1: Failure to obtain building permits for all signs placed, security cameras installed, and electric wiring running to a shed with lights running throughout the property. Count 2: Failure to obtain HARC certificate of appropriateness for all signs placed, security cameras installed, and electric wiring running to a shed with lights running throughout the property. Count 3: Failure to receive inspections for electrical work done on the property.

### Sponsors:

### Indexes:

### Code sections:

### Attachments:

Date	Ver.	Action By	Action	Result
9/25/2019	1	Code Compliance Hearing	Continuance	

### Case # 19-463

G. B & B-B Registries, LLC  
210 Simonton Street Lot  
Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions  
Sec. 14-40 Permits in historic districts  
Sec. 14-262 Request for inspection  
Officer Dorian Patton  
Certified Mail: 8-9-2019  
Initial Hearing: 9-25-2019

### Continued from 25 Sept 2019

**Count 1:** Failure to obtain building permits for all signs placed, security cameras installed, and electric wiring running to a shed with lights running throughout the property. **Count 2:** Failure to obtain HARC certificate of appropriateness for all signs placed, security cameras installed, and electric wiring running to a shed with lights running throughout the property. **Count 3:** Failure to receive inspections for electrical work done on the property.

