



## Legislation Details (With Text)

**File #:** 21-6809      **Version:** 1      **Name:**  
**Type:** Action Items      **Status:** Passed  
**File created:** 3/15/2021      **In control:** Contractors Examining Board  
**On agenda:** 4/7/2021      **Final action:** 4/7/2021

**Title:** HEARING:  
Case #21-0583  
Contractor: Frank White, Key West Boyz Co., Inc.  
Inspector: Troy Montero

Date of Violation(s) 11/05/2020

Code Violations  
Count 1: Sec. 14-37 -Building without a permit  
Address: 1617 White St, Key West, Fl.  
Permit: 21-0583  
Code Case #20-01335

On 11/05/2020 the City of Key West Code Compliance Department received an anonymous complaint regarding work without the benefit of required permitting. Code Officer Troy Montero responded to the complaint and found a complete accessory structure being constructed without the benefit of a building permit.

Count 2: F.S. 489.113 (2) (a) & (b)

Officer Montero photographed a sewage grinder pump and plumbing lines being installed without the benefit of a plumbing permit. Mr. White is not licensed to perform plumbing.

### Sponsors:

### Indexes:

### Code sections:

**Attachments:** 1. Cert. Mail & Lt., 2. Photos 20-01335, 3. Case Details update, 4. 21-0583AccessoryStructurePermitDetails, 5. 21-00849PlumbingPermitDetails, 6. 21-0910ElectricPermitDetails, 7. CodeNotice

Date	Ver.	Action By	Action	Result
4/7/2021	1	Contractors Examining Board	Approved	Pass

HEARING:  
Case #21-0583  
Contractor: Frank White, Key West Boyz Co., Inc.  
Inspector: Troy Montero

Date of Violation(s) 11/05/2020

Code Violations  
**Count 1: Sec. 14-37 -Building without a permit**

Address: 1617 White St, Key West, FL.  
Permit: 21-0583  
Code Case #20-01335

On 11/05/2020 the City of Key West Code Compliance Department received an anonymous complaint regarding work without the benefit of required permitting. Code Officer Troy Montero responded to the complaint and found a complete accessory structure being constructed without the benefit of a building permit.

**Count 2: F.S. 489.113 (2) (a) & (b)**

Officer Montero photographed a sewage grinder pump and plumbing lines being installed without the benefit of a plumbing permit. Mr. White is not licensed to perform plumbing.

Sponsors: Mr. Justice

Attachments: