



Legislation Details (With Text)

File #: 22-2447 **Version:** 1 **Name:**
Type: Action Items **Status:** Passed
File created: 3/29/2022 **In control:** Contractors Examining Board
On agenda: 6/1/2022 **Final action:** 6/1/2022

Title: (Hearing)
Case: #22-00546
Address: 3735 Paula Ave.
Contractor: Pool Tech of Miami, Inc.
(Frank De Izaguirre)

Code Officer: Igor Timus

Date of Violation(s) 03/03/2022
Case: #22-00546 (Building Ordinance)

Code Violation:
Count 1: Sec. 14-37 - Work performed without a permit

Address: 3735 Paula Ave.

On 3/03/2022 During an area canvas Officer Igor Timus of the City of Key West Code Compliance Dept. heard noises at 3735 Paula Ave. he observed and photographed construction debris and a laborer standing outside of 3735 Paula Ave. He spoke with the owner's mother and she explained that the worker who works for Pooltech of Miami, was preparing the pool for resurfacing. No permits were found in the system. A Stop Work Order was placed until permits were obtained.

Sponsor: Mr. Ramsingh

Sponsors:

Indexes:

Code sections:

Attachments: 1. Case Detail 22-00546, 2. Pooltech of Miami CertifiedMail4.6.22CEB, 3. 3735 Paula St 1, 4. 3735 Paula St 2, 5. 3735 Paula St. 3

Date	Ver.	Action By	Action	Result
6/1/2022	1	Contractors Examining Board	Approved	Pass
4/6/2022	1	Contractors Examining Board	Postponed	Pass

(Hearing)

Case: #22-00546
Address: 3735 Paula Ave.
Contractor: Pool Tech of Miami, Inc.
(Frank De Izaguirre)

Code Officer: Igor Timus

Date of Violation(s) 03/03/2022
Case: #22-00546 (Building Ordinance)

Code Violation:

Count 1: Sec. 14-37 - Work performed without a permit

Address: 3735 Paula Ave.

On 3/03/2022 During an area canvas Officer Igor Timus of the City of Key West Code Compliance Dept. heard noises at 3735 Paula Ave. he observed and photographed construction debris and a laborer standing outside of 3735 Paula Ave. He spoke with the owner's mother and she explained that the worker who works for Pooltech of Miami, was preparing the pool for resurfacing. No permits were found in the system. A Stop Work Order was placed until permits were obtained.

Sponsor: Mr. Ramsingh