



## Legislation Text

---

**File #:** 19-3708, **Version:** 1

---

### **Case # 18-2020**

Robert Chinnis Construction, Inc

Robert R. Chinnis - RA

506 Southard Street

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-37 Building permits; professional plans; display of permits; address; exceptions

Sec. 14-40 Permits in historic districts

Sec. 14-262 Request for inspection

Officer Jorge Lopez

Hand Served: 2-27-2019

Initial Hearing: 3-27-2019

### **Continued from 24 April 2019 for compliance**

**Count 1:** Failure to obtain a permit for plumbing work performed in the rear side exterior of the building. **Count 2:** Failure to obtain a permit for electrical work performed on the rear side of the building. **Count 3:** Failure to obtain a certificate of appropriateness for plumbing and electrical work performed on the rear side of the building. **Count 4:** Failure to obtain a required electrical inspection for electrical work performed on the rear side of the building.